



## Installation Details

Location: Hejiashan Cement Co., Ltd.

[www.jiangshanhu.com](http://www.jiangshanhu.com)

Model:  S50

Area: Main circulating cooling pipe

Problem: During the cement production process, the cooling water pipes were heavily scaled, and a large amount of scale accumulated, causing blockages in the piping system, which seriously affected production.

The piping system was blocked every half a month, which required shutting down and cleaning each time, as well as replacing part of the pipes once a year.

Result: **1 month** after the installation of Vulcan S50, the pipes were still not clogged, so the customer is satisfied with the Vulcan effect.

Installer: Xinriyuan

