

Vulcan Effect in the Bread Oven

Installation Details

Location: A metro food store


Québec, Canada

Model:  Vulcan 5000

Treatment area: The bread oven

Problem: Often reparation and needed to clean manually

Installed by: Gestion L.B. Inc



Vulcan 5000
Remove the insulation cotton and install the impulse bands.

The bread oven before Vulcan installation.

The scale deposits were cleaned and Vulcan 5000 was installed.



Vulcan effect

After 6 months with Vulcan, very little scale has been formed.

