



Heat Sinks



Brackets



Stampings and Light Shields



Reflectors



Small Lamps



Valves and IBC Components

Installation Details

Location: Sea Link Die Casting (Kunshan) Co., Ltd.

Model:  S100

Area: Cooling tower system

Problem: The cooling tower fills were scaled heavily and difficult to remove, resulting in poor heat transfer efficiency and a high rate of product manufacturing defects.

Result: The cooling tower system required manual cleaning 4-6 times a year. **6 months** after the installation of Vulcan S100, **no new scale has been formed** in the cooling system.

Installer: Xinriyuan Company



Sea Link Die Casting (Kunshan) Co., Ltd.

Vulcan S100



Remove the pipe insulation and install Vulcan S100.