



## Installation of Vulcan water treatment



**Installation site:** White Castle #49, Indianapolis, USA  
**Model:** Vulcan 3000 (installed on the in the line after the carbon filters)  
Vulcan 5000 (installed on the main inlet line, before the 5 micron carbon filters)

### White Castle #49 – April 14

The R2D2 had been in service only 3 weeks and you can see the stainless steel is already etched at the water line. The water feeding the R2D2 was changed to being fed after the standard 25 micron but before the 5 micron carbon filters.

The Vulcan 5000 is located in the main line, but before the 25 micron filter. The Vulcan 3000 is located in the line after the carbon filters.

The installation of Vulcan 3000 and Vulcan 5000 solved this hard build-up problem successfully.



Before Vulcan installation - calcium lines present on stainless steel after only 3 weeks.

### Before using Vulcan - April 14

Hard calcium deposits in the pan.



### After installing Vulcan - May 12

95% less calcium deposits in the pan



After this very successful using of Vulcan in our White Castle restaurant #49 in Indianapolis, we installed the Vulcan 3000 and Vulcan 5000 device also in the White Castle restaurant #32 in New York and the White Castle restaurant #38 in New Jersey.