

YONGXING CHEMICAL

Installation Details

Location: Yongxing Chemical Co., Ltd.

Model:  S100

Area: Before the plate heat exchangers

Problem: The chemical industry consumes a lot of water, and the plate heat exchanger was heavily scaled, resulting in reduced heat transfer efficiency and reduced water flow. It needed to be cleaned **once a month**, and the work efficiency was low.

Result: The plate heat exchanger does not need to be cleaned until about **6 months** after installation of Vulcan.

Installer: Xinriyuan



Yongxing Chemical Co., Ltd. is mainly engaged in the production and sales of chemical raw materials.

Vulcan S100 was installed in front of the plate heat exchangers

