



## INSTALLATION DETAILS

**Location:** AURA HOTEL  
8320 Balatonfüred,  
Munkácsy M. u.5., Hungary  
[www.aura-hotel.hu](http://www.aura-hotel.hu)

**Model:**  Vulcan S50

**Area:** Main water inlet pipe

**Installed by:** VARÁZSMAG Kft



## PURPOSE

### General protection of the piping system.

They had to maintain the ice-machines monthly, the faucets and shower heads were blocked by the scale after 6 months of opening the Hotel, the tiles and the shower walls were extremely scaly. They cleaned the bathrooms manually, that lasts for hours. The faucets had to be changed and the ice machine had to be repaired.

## RESULTS

The faucets and tiles can be cleaned by wiping the powder-formed scale. The ice-machine working properly. The dishwasher gives out perfectly shiny and spotless dishes and glassware.



*"I really appreciate that all machines and equipment work properly again in the kitchen and I can focus on creating and serving the best meals to our guests."*

Sándor Böröcz  
Head Chef