



Baijia Lake Villa

Installation Details

Location: Baijia Lake Villa, China
Model: Vulcan 5000
Area: Installed in a villa residence
Problem: The toilet and showerheads were obviously blocked by scale
Installed by: Xinriyuan Company

3 months after installing Vulcan 5000

Before installing Vulcan 5000, the scale had to be cleaned manually. 3 months after the installation, there was no scale deposit in the bottom of the kettle or the showerheads, and the scale in the water pipe and toilet was significantly reduced.

