



Review

Water Treatment System VULCAN

In June, Junels GmbH installed the **Vulcan S50 system in the building of the Latvian Bank in Riga**. The effect of the plant was already apparent after 3 months, when water with pieces of scale deposits appeared at some water tapping points.

In October Junels Ltd. installed the **Vulcan 5000 system in the building of the Bank of Latvia in Jurmala**. After about 4 months, it was found that the hot water pipes were intensely cleaning themselves from the scale and rust deposits. However, as the scale deposits were very persistent, the process of decalcification of the pipelines took 24 months after installation.

Since the installation of the system, no scale deposits have been found on the shower heads and taps.

The systems are doing their job, no more scale and rust deposits have formed. When installing the equipment on old water supply systems, it is advisable to check the connection points of the pipes more often, because there are often leaks in the connections during the decalcification process.

The survey of the water treatment plant Vulcan was made on request of Junels GmbH.

Andris Nikitins

*Head of the Technical Department
of the Bank of Latvia*

Normunds Vasilevs

*Engineer for building systems of the
technical department of the Bank of Latvia*