

To: Eye in Electronics CEO

Review of the VULCAN equipment

Installation location: Main water feed of Mother and baby convalescent home — Telshe Stone.

System installed: VULCAN S100

The system was installed on our main source of water supply in the main water supply to the building.

Before installing VULCAN, we treated the scale with water softeners, which required large amounts of salt, cleaning and maintenance.

- ▶ For dishwashing systems, hot water for showers and washing machines we used salt softeners.
- ▶ Drinking water boilers and kettles in the wards required weekly cleaning with tartaric acids.
- ▶ Shower heads needed frequent treatment to remove scale deposits.

After installing the VULCAN system:

- ▶ We have stopped consuming acids to clean the drinking water containers. They can now be cleaned by hand.
- ▶ Water softeners have been taken out of operation and no more salt is used!
- ▶ The dishwashers are clean!
- ▶ The shower heads < After a period of cleaning all the pipes > do not need cleaning and no replacement is required.

Savings:

- ▶ In cleaning materials, filters, maintenance time, and not needing to stop the use of facilities just for the sake of cleaning the water systems.
- ▶ Financial savings: the price of a VULCAN system is covered within a reasonably short period of time.

Best regards,
 G. P.
 General Manager



Mother and baby convalescent home.



The salt bags on the left side are no longer used and replaced with Vulcan.