

Vulcan S100 Installation

To the Kostečka Team,

The Vulcan device was installed on the lime oven, which usually required extensive scale cleaning every 3 months. It has been 4 months since the Vulcan S100 was installed, and the scale problems have reduced significantly.

The pipes and production equipment require much less cleaning now. We are very satisfied with the performance of the Vulcan S100.

Best Regards,
The Mondi Group



Mondi Štětí a.s manufacturing plant in the Czech Republic



Deposit removed from pipe after Vulcan installation



Vulcan S100



Installation of Vulcan S100 on lime kiln

