

The Cooling System in the Poultry Farm



Installation details

Location: 3 chicken farms in Morocco


Area:

- 6 cooling systems
- drinking water of hens

Model:  Vulcan S10

Result: After Vulcan S10 had been installed for 2 weeks, scale had been softer and easily removed with a water gun.

Installed by: STE ETCT INDUSTRIE



Vulcan S10 was installed in the water main to treat 6 cooling systems in 3 chicken farms.



Without any water treatment, scale was hard like stones.



After Vulcan S10 had been installed for 2 weeks, scale had been softer and easily removed with a water gun.