

Dear Sirs,

After multiple problems with scale build-up in our irons and laundry equipment we decided to try and solve this situation. After much research, we finally found the solution we were looking for. We chose the innovative line of water treatment, Vulcan. The Vulcan S25 unit was installed.

Up until now, the results obtained have been entirely satisfactory; not only because the scale does not stick to surfaces anymore, but also because of the raised quality of the laundry which has a less-abrasive effect on the clothes. This has helped increase our service quality and customer satisfaction.

For the above reasons, we certify the complete effectiveness of the Vulcan S25 device installed in our company.

Sincerely,

LAS PAMAS
C/ Puerto Rico, 2 Pta. 3 – 2ª Ofic. 3
35010 – Las Palmas de Gran Canaria
Telf.: 902 226 047 • Fax: 928 226 008

TENERIFE
Subida a El Mayorazgo, 16
38009 – Santa Cruz de Tenerife
Telf.: 922 236 030 • Fax: 922 211 048



Esther Meca Cervera
Jefa Dpto. Sistema Integrado de Gestión
Calidad, Medio Ambiente, PRL y Organización
RALONS LAVANDERÍA, S.L.
GRUPO RALONS

