

Installation Details

Location: Le Nobilis Residences

(269 flats in the building)

Blainville, Québec,

Canada

Scale problem: Had to clean the scale with chemicals

manually

Model/Area: 1 x V5000 for the hot water recirculation

1 x S50 for the water entrance

Treatment area: Whole piping system

Testing period: 12 months

Installed by: Gestion L.B. Inc

www.calcairesolution.com

The Results

The good comments of the director of the residence:

After 1 year of use, the results are positive, the cleaning of limestone in kitchen appliances has decreased by **75%**. We have done tests on the filters in the kitchen, we stopped changing the kitchen's water filters in 2018 when installing the Vulcan system. In 2020, the old filters of 2018 are made immaculate white as if they were new, we can affirm that the **Vulcan system makes it possible to stop filter changes**, with a fairly high efficiency that the Vulcan system was used to clean the old filters clogged.

We also noticed a complete stop of the service calls concerning the limestone in the showers of housing. Before the Vulcan system, we had to clean the shower heads in each of the homes every 16 months. Since the installation of the system, no customer has requested service for cleaning.

In summary, we are completely satisfied with the system, and we can say that customer service and water quality have been greatly improved.



