

# Example of installation of VULCAN

The rust water from inside coved pipe by coating




- Installation day : 23/Jan-2008
- Installation place : Sizuoka pref(JPN)  
office BLD. of pharmaceutical company  
outside pipe room
- Installation type : VULCAN S25
- Installation pipe size : 100A  
inside covered by coating
- Problem : Rust water flew every day  
in the morning

## The picture of the installation

Especially, the rust water flew from tap at 4 floor.  
every morning these rust water gathered up  
into the plastic holder and water color comparison  
to day by day.

After the 40 days later, from the VULCAN installation.  
This problem improved in almost colorless water,  
by the VULCAN system.



Water system



A gathered paper the rust and thickness  
water color decreased day by day

**CATALINA**